


Mitsuba Replacement Starters



168452

OSGR

12V, CW, 1.4kw, 9T

Replace: SM302-18

Lester: 16845

PIC: 191-127

Note: 190-348 Denso Version.
16845N New



169022

OSGR

12V, CW, 1.0kw, 9T

Replace: SM302-07, SM302-25

Lester: 16902

PIC: 191-129

Note: 190-358 Denso Version



169142

OSGR


12V, CW, 1.4kw, 9T

Replace: SM302-04, SM302-16

Lester: 16914

PIC: 191-125

Note: 190-354 Denso 1.4kw,
190-358 Denso 1.0kw.



169602

PMOSGR

12V, CW, 1.6kw, 9T

Replace: SM402-03

Lester: 16960

PIC: 191-131

Note: 190-247 Denso Version



16975R

PMOSGR


12V, CW, 1.6kw, 9T

Replace: SM402-05,
SM402-05N

Lester: 16975

PIC: 191-132

Note: 190-246 Denso Version



174742

PMOSGR

12V, CW, 1.6kw, 9T

Replace: SM402-13,
SM402-13N

Lester: 17474

PIC: 191-139


Note: 190-389 Denso Version

All OE company name and part number are for reference purpose only.

Metro Auto Industrial nc.
2128 Pomona Blvd. Pomona, CA 91768
Toll Free: 800-263-8761


Tel: (909) 629-2700 Fax: (909) 629-2721
e-mail: info@metroautinc.com
web: www.metroautinc.com

Mitsuba Replacement Starters



175822

PMOSGR
12V, CW, 1.6kw, 9T
Replace: SM422-01
Lester: 17582
PIC: 191-151
Note:




175912

PMOSGR
12V, CW, 1.6kw, 9T
Replace: SM422-02
Lester: 17591
PIC: 191-152
Note: 191-160 Later Version
SM422 Series can replace it.

**No Photo
Available**

176612

PMOSGR
12V, CW, 1.6kw, 9T
Replace: SM422-03
Lester: 17661
PIC: 191-150
Note:



177281

PMOSGR
12V, CW, 1.6kw, 9T
Replace: SM442-01
Lester: 17728
PIC: 191-161
Note: 177282 REMAN



177291

PMOSGR
12V, CW, 1.6kw, 9T
Replace: SM442-02
Lester: 17729
PIC: 191-160
Note: 177292 REMAN

All OE company name and part number are for reference purpose only.

Metro Auto Industrial Inc.
2128 Pomona Blvd. Pomona, CA 91768
Toll Free: 800-263-8761

Tel: (909) 629-2700 Fax: (909) 629-2721
e-mail: info@metroautoinc.com
web: www.metroautoinc.com